



**German Intensity Standard
VD13882/3940 Scale**

- 0 Not detectable
- 1 Very weak
- 2 Weak
- 3 Distinct
- 4 Strong
- 5 Very strong
- 6 Extremely strong
- < less than

SMRC RRRC - Field Based Ambient Odour Intensity Assessments		
March 2021		
	Date	MAR
	Wind	SE, SSE Moderate
Street Location	I.D.	Average
Cnr. Merrifield & Roe Hwy	1	0
Merrifield (middle)	2	0
Cnr. Beasley & Merrifield	3	0
Beasley	4	0
Cnr. Beasley & Merrifield	5	0
Merrifield (middle)	6	0
Cnr. Merrifield & Roe Hwy	7	0
Merrifield (middle)	8	0
Stenton Corner	9	0
Bosworth Place	10	0

Assessment Area 3

Cnr. Merrifield & Roe Hwy	1	0
Cnr. Beasley & Merrifield	2	0
Cnr. South Street & Darian Drive	3	0
Cnr. Darian Drive & Trident Terrace	4	0
Trident Terrace (middle)	5	0
Cnr. Trident Terrace & Plover Drive	6	0
Cnr. Arlington & Vahland	7	0
Arlington Drive Elbow	8	0
Cnr. Vahland & South Street	9	0

Assessment 4