



**German Intensity Standard  
VD13882/3940 Scale**

- 0 Not detectable
- 1 Very weak
- 2 Weak
- 3 Distinct
- 4 Strong
- 5 Very strong
- 6 Extremely strong

| <b>RRG – Canning Vale Centre<br/>– Field Based Ambient Odour Intensity Assessments</b> |             |                |
|--|-------------|----------------|
| <b>June 2023</b>   |             |                |
|  | <b>Date</b> | <b>JUN</b>     |
|  | <b>Wind</b> | <b>SSE</b>     |
| <b>Street Location</b>   | <b>I.D.</b> | <b>Average</b> |

**Assessment 4**

|                                     |          |          |
|-------------------------------------|----------|----------|
| Cnr. Merrifield & Roe Hwy           | <b>1</b> | <b>0</b> |
| Cnr. Beasley & Merrifield           | <b>2</b> | <b>0</b> |
| Cnr. South Street & Darian Drive    | <b>3</b> | <b>0</b> |
| Cnr. Darian Drive & Trident Terrace | <b>4</b> | <b>0</b> |
| Trident Terrace (middle)            | <b>5</b> | <b>0</b> |
| Cnr. Trident Terrace & Plover Drive | <b>6</b> | <b>0</b> |
| Cnr. Arlington & Vahland            | <b>7</b> | <b>0</b> |
| Arlington Drive Elbow               | <b>8</b> | <b>0</b> |
| Cnr. Vahland & South Street         | <b>9</b> | <b>0</b> |