



German Intensity Standard  
VD13882/3940 Scale

- 0 Not detectable
- 1 Very weak
- 2 Weak
- 3 Distinct
- 4 Strong
- 5 Very strong
- 6 Extremely strong
- < less than

**RRG - Canning Vale Centre**

**Field Based Ambient Odour Intensity Assessments**

**Dec 2024**

**Assessment Area 3**

Street Location	Date	DEC
	Wind	SE
Street Location	I.D.	Average
Cnr. Merrifield & Roe Hwy	<b>1</b>	0
Merrifield (middle)	<b>2</b>	0
Cnr. Beasley & Merrifield	<b>3</b>	0
Beasley	<b>4</b>	0
Cnr. Beasley & Merrifield	<b>5</b>	0
Merrifield (middle)	<b>6</b>	0
Cnr. Merrifield & Roe Hwy	<b>7</b>	0
Merrifield (middle)	<b>8</b>	0
Stenton Corner	<b>9</b>	0
Bosworth Place	<b>10</b>	0